

**TABLE 1**  
**Benzene Concentrations Reported for Soil Samples Collected by Plaintiffs During Phase 1 Judicial Inspections**  
 Chevron, Oriente Region, Ecuador

Inspection Type	SiteID	SampleID	Matrix	SampleDate	Benzene Concentration (mg/kg)	Report	Report Date
Plaintiff	LANorte_PS	LAN-PT1-C3	Soil	28-Jan-05	<0.05	Informe Pericial de la Inspección Judicial Realizada a la Estación de Procuccion Lago Agrio Norte	01-Aug-05
Plaintiff	SA-010	SA 10-S1 0.85 - 1.29 M	Soil	29-Sep-04	<0.025	Informe del Perito de la Inspeccion Judicial en el pozo Sacha 10	
Plaintiff	SA-051	SA51-N2 1.70 - 2.25 M	Soil	30-Sep-04	<0.025	Informe del Perito de la Inspeccion Judicial en el pozo Sacha 51	27-Apr-05
Plaintiff	SA-051	SA51-NE2 1.25 - 1.77 M	Soil	01-Oct-04	<1	Informe del Perito de la Inspeccion Judicial en el pozo Sacha 51	27-Apr-05
Plaintiff	SA-051	SA51-S2 1.23 - 1.50 M	Soil	30-Sep-04	<0.025	Informe del Perito de la Inspeccion Judicial en el pozo Sacha 51	27-Apr-05
Plaintiff	SA-053	SA-53 NW4 1.35-1.40M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW4 2.7-3.55 M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW4 4.10-4.40 M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW5 0.85-1.25 M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW5 3.0-3.40 M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW5 A 1.70-2.55 M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW5 B 1.70-2.55 M	Soil	01-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW6 2.0-2.30 M	Soil	02-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW6 5.55-5.95 M	Soil	02-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW6 6.28-6.80 M	Soil	02-Sep-04	<0.05	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-094	SA-94 NW4 2.75-2.90 M	Soil	08-Sep-04	<0.005	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SA-094	SA-94 NW4 4.75-4.85 M	Soil	08-Sep-04	<0.005	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SA-094	SA-94 PIT 3 SB1 1.70-2.10 M	Soil	08-Sep-04	<0.005	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SA-094	SA-94 SW5 2.20-2.55 M	Soil	08-Sep-04	<0.005	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SA-094	SA-94 SW5 2.95-3.15 M	Soil	08-Sep-04	<0.005	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SSF-48	SH48 SE3 2.75-3.00M	Soil	14-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-N3 1 - 1.2 m	Soil	09-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE3 1.55 - 1.7 m	Soil	14-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE3 2.28 - 2.55 m	Soil	14-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE3 4 - 4.25 m	Soil	14-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE3 5.5 - 5.8 m	Soil	14-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE4 1.5 - 1.7 m	Soil	13-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE4 2.20-3.40M	Soil	13-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE4 3.68 - 3.94 m	Soil	13-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE5 0 - 0.2 m	Soil	13-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SE5 0.2 - 0.4 m	Soil	13-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SW2 1.2 - 1.3 m	Soil	09-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SW2 1.37 - 1.7 m	Soil	09-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SW3 0.85 - 1.31 m	Soil	09-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSF-48	SH48-SW3 4.5 - 5.1 m	Soil	09-Sep-04	<0.005	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SSFSuroeste_PS	SSF-SW-PNT-SCI2 0.1-0.35M	Soil	06-Oct-04	<0.025	Informe de Perito Oscar M. Davila--Estacion Shushufindi Suroeste/ Expert Report of Oscar M. Davila for Shushufindi Southwest Production Station	28-Feb-05
Plaintiff	SSFSuroeste_PS	SSF-SW-PNT-SCIII 0.3-0.6M	Soil-Lith	06-Oct-04	<5	Informe de Perito Oscar M. Davila--Estacion Shushufindi Suroeste/ Expert Report of Oscar M. Davila for Shushufindi Southwest Production Station	28-Feb-05

**TABLE 2**  
**Benzene Concentrations Reported for Water Samples Collected by Plaintiffs During Phase 1 Judicial Inspections**  
 Chevron, Oriente Region, Ecuador

Inspection Type	SiteID	SampleID	Matrix	SampleDate	Benzene Concentration (mg/L)	Report	ReportDate
Plaintiff	SA-010	SA 10 S1 0.25-0.45	Muddy Water	29-Sep-04	<0.011	Informe del Perito de la Inspeccion Judicial en el pozo Sacha 10	
Plaintiff	SA-051	SA 51 NE2 0.45M	Muddy Water	01-Oct-04	<0.011	Informe del Perito de la Inspeccion Judicial en el pozo Sacha 51	27-Apr-05
Plaintiff	SA-053	SA-53 NW4 3.50 M	Muddy Water	01-Sep-04	<0.002	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-053	SA-53 NW6 4.0 M	Muddy Water	02-Sep-04	<0.002	Informe de la Inspeccion Judicial Realizada el 01 de Septiembre de 2004 en el Pozo Sacha 53	29-Nov-04
Plaintiff	SA-094	SA-94 NW4 1.7 M	Muddy Water	08-Sep-04	<0.002	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SSF-48	SH48-SE3 PROF: 4.70M	Muddy Water	14-Sep-04	<0.002	Inspeccion Judicial Del Pozo Shushufindi 48	08-May-05
Plaintiff	SA-094	SA-94 MA2	Surface Water	08-Sep-04	<0.002	Document.pdf (More of SA-94 Plaintiff's Report)	
Plaintiff	SSFSuroeste_PS	SSF-SW-PNT-II-H1	Surface Water	06-Oct-04	<0.002	Informe de Perito Oscar M. Davila--Estacion Shushufindi Suroeste/ Expert Report of Oscar M. Davila for Shushufindi Southwest Production Station	28-Feb-05
Plaintiff	SSFSuroeste_PS	SSF-SW-PNT-SCI2	Surface Water	06-Oct-04	<0.002	Informe de Perito Oscar M. Davila--Estacion Shushufindi Suroeste/ Expert Report of Oscar M. Davila for Shushufindi Southwest Production Station	28-Feb-05
Plaintiff	SSFSuroeste_PS	SSF-SW-PNT-SCIII	Surface Water	06-Oct-04	<0.002	Informe de Perito Oscar M. Davila--Estacion Shushufindi Suroeste/ Expert Report of Oscar M. Davila for Shushufindi Southwest Production Station	28-Feb-05